### SCIENTIFIC DATA SYSTEMS, INC.

**Depth Tension Line Speed Panel** 

# **DTLS Manual**

This document contains proprietary information. Copyright © 2015 Scientific Data Systems, Inc. All rights reserved.

# **DTLS Manual**

This document contains proprietary information. Copyright © 2015 Scientific Data Systems, Inc. All rights reserved. 3401 Bacor Road Houston, Texas 77084, USA Phone: 1-281-398-1612 E-mail: sds.info@warriorsystem.com Website: www.warriorsystem.com Created September 5, 2018 Windows® is a registered trademark of Microsoft Corporation in the United States and/or other countries. All other product names are trademarks of their respective companies.

# **Table of Contents**

T/	ABLE OF CONTENTS	.3
1	DTLS HARDWARE	.5
	INTRODUCTION DEPTH PANEL OPERATION FIG 1.1 DTLS FACE PLATE FIG 1.2 DTLS REAR PLATE	.5 .5 .7 .8
2	DTLS CONNECTOR WIRING	.9
	INTERCONNECTION CABLES	.9
3	DTLS METER PROGRAMING 1	11
	SETUP FOR DEPTH COUNTER 1	1  2  3
4	DTLS THROUGH WARRIOR SOFTWARE 1	17
	USB COMMUNICATIONS	17
5	DTLS HARDWARE 1	9
	SCHEMATIC 1       1         SCHEMATIC 2       1         SCHEMATIC 3       1         Fig 6.1 Schematic page 1       1         Fig 6.2 Schematic page 2       1         Fig 6.3 Schematic page 3       1         Fig 6.4 PCB       1	9  9 20 21 23 24
6	DTLS HARDWARE	27

# **1 DTLS Hardware**

#### Introduction

The Depth, Line Speed and Line Tension Panel uses three industrial process Meters to provide simultaneous digital readout of the three measurements. Meter 1 is setup in a counting mode and can accommodate virtually any encoder resolution. Meter 2 is setup in a rate \ counter indicator mode and runs from the same encoder signals as Meter 1. Meter 3 senses a 4 - 20 ma signal from a pressure transducer connected to the measure head weight indicator system. Meters for other types of line weight sensor are available.

The panel is intended to be powered by a 12 volt battery and contains a power supply providing regulated 12.0 volts and 5.0 volts for indicator and encoder power. The panel also provides 12 volts excitation for the pressure transducer. The encoder pulses are converted to depth and direction signals and routed to the depth and line speed meters and are also buffered and output to the rear panel connectors for input to the logging system. A retransmitted 4 - 20 ma signal is also available at the rear panel also for input to the logging system.

#### **Depth Panel Operation**

Depth entries and alarm setup points are entered from the key pads of each meter. Depth1 meter contains the alarm for minimum depth. If the depth counter becomes less than this minimum, it will activate the depth alarm. Depth2/Line Speed meter contains the alarm for maximum line speed. If the line speed becomes greater than this maximum, it will activate the overspeed alarm. Depth2 meter will display both a depth and the line speed, which can be selected by pressing the DISP-key. Any of the alarms will activate an audible alarm, front panel LED, and a rear panel external connector. The audio alarm can be silenced for the duration of the cause of that alarm by pressing the ALM DIS button. Once the alarm condition has passed, the audio alarm will be enable again for the next alarm.

To enter a new preset depth on either depth meter, press the P2-key of that meter. The last preset depth will be displayed. The key directly under each digit will change the value of that digit. After the desired changes have been made, press the E-Key to enter the value into preset depth memory. To update the depth to the preset value, press the R-key to reset the depth.

To enter new alarm values on either depth meter, press the P1-key of that meter. After changes have been made, press the E-key to enter the value into preset alarm memory. To enter a new alarm value on the line tension meter, press the PAR-key. The F1-key and F2-key can then be used to change the value. Press the PAR-key again to store the new alarm value



Fig 1.1 DTLS Face Plate



Fig 1.2 DTLS Rear Plate

# **2 DTLS Connector Wiring**

#### **Interconnection Cables**

The cable to connect the depth panel buffered encoder output to the tool Interface panel has the following connections:



The cable to connect the depth panel encoder input to the depth encoder has The following connections:

Depth Panel 7 Pin Male

Depth Encoder 7 Pin Female



The cable for the retransmitted line tension from the depth panel to the system Tool interface panel has the following connections:



The cable for the depth panel line tension input to the pressure transducer has The following connections:



## **3 DTLS Meter Programing**

#### **Setup for Depth Counter 1**

Two sets of DIP switches must be set for proper function of the Depth meter. Switch one is located on the back of the meter. Switch two is located on the right side, as viewed from the front,

(SW-1 ON Meter - 1, 4, 7, 8 ON/DOWN and 2, 3, 5, 6 OFF/UP) (SW-2 ON Meter - 1, 2 ON/DOWN and 3, 4, 5, 6, 7, 8, 9, 10 OFF/UP)

Programming may only be accomplished by activating the `program enable' switch at the rear of the panel. Other than changing the scale factor, reprogramming should only be necessary upon installation of a new meter.

CODE	ENTRY		
41	1	Set unit personality to COUNTER	
43	2	Set inputs to COUNT with UP/DOWN Control	
44	1	Set to SINGLE EDGE COUNTING	
45	2	Set scale multiplier to .01	
46	2	Set decimal point and leading zero blanking	
51	-2	Set reset mode to manual reset to preset	
52	-6	Set Output1 Alarm control to Boundry	
53	0.01	Set Output1 Time Delay to minimum	
54	3	Set Output2 Termination to Terminate at Reset	
55	0.01	Set Output2 Time Delay to minimum	
61	4	Set Right hand Dummy Zeros to None	
66	2	Set Operator enabled functions to Reset and Preset only	

#### With the settings above, to read out in feet (or meters)

\* Scale factor = 100 divided by encoder pulses per foot (or encoder pulses per meter)

JP5 Setting	120 ppr	400 ppr	600 ppr	1200 ppr
1-2 No Divide	0.8333	0.2500	0.1667	0.0833
3-4 /2	1.6667	0.5000	0.3333	0.1666
5-6 /4	3.3333	1.0000	0.6666	0.3333
7-8 /8	6.6666	2.0000	1.3333	0.6666

# \*Scale Factors - Note placing a "-" sign in front of scale factor reverses encoder direction.

#### Setup for Depth Counter 2/ Line Speed

Two sets of DIP switches must be set for proper function of the Depth/Line Speed meter. Switch one is located on the back of the meter. Switch two is located on the right side, as viewed from the front,

(SW-1 ON Meter - 1, 4, 7, 8 ON/DOWN and 2, 3, 5, 6 OFF/UP) (SW-2 ON Meter - 1, 2,10 ON/DOWN and 3, 4, 5, 6, 7, 8, 9 OFF/UP)

Programming may only be accomplished by activating the `program enable' switch at the rear of the panel. Other than changing the scale factor, reprogramming should only be necessary upon installation of a new meter.

CODE	ENTRY		
41	1	Set unit personality to RATE METER/COUNTER	
42	3	Set Reset for both Rate and Counter	
43	2	Set inputs to COUNT with UP/DOWN Control	
44	1	Set to SINGLE EDGE COUNTING	
45	2	Set scale multiplier to .01	
46	2	Set counter decimal point and leading zero blanking	
51	1	Set Output1 to Rate and Output2 to Counter	
52	6	Set Rate Alarm control to Boundry	
53	0.01	Set Rate Time Delay to minimum	
54	3	Set Counter Termination to Terminate at Reset	
55	0.01	Set Counter Time Delay to minimum	
56	-2	Set Reset Counter to Preset 2	
61	4	Set Right hand Dummy Zeros to None	
62	1	Set Time Rate to 1 Second	
63	1	Set Rate Update Time	
64	3	Set Rate Scale Multiplier to 10	
65	2	Set Rate decimal point and leading zero blanking	
66	2	Set Operator enabled functions to Reset and Preset only	

With the settings above, to read out in feet per minute (or meters per minute) \* Scale factor = 60 divided by encoder pulses per foot (or meter)

JP5 Setting	120ppr	400ppr	600ppr	1200ppr
1-2 No Divide	0.5000	0.1500	0.1000	0.0500
3-4 /2	1.0000	0.3000	0.2000	0.1000
5-6 /4	2.000	0.6000	0.4000	0.2000
7-8 /8	4.0000	1.2000	0.8000	0.4000

Scale factor for the Depth 2 Counter is the same as the Depth 1 Counter above.

#### Setup of Line Tension

Programming may only be accomplished by activating the `program Enable' switch at the rear of the panel. Press the PAR (Parameters) key to enter Program mode and select parameter groups. Use the F1 and F2 keys to change Selections Set each of the program groups as follows

Display	Parameter	Setting		
rAn6E	Input Range – 20MA	0.02A		
dECPt	Display Resolution – Full Lbs.	0		
round	Display Rounding Increment	1		
FILtr	Filter Setting	2.0		
bAnd	Filter Enable Band	10		
PtS	Scaling Points – Use 2 of 16 possible	2		
StYLE	Keyboard Entry or Calibration Applied	KEY or APLY		
InP 1	Low Input reading in MA	*4.000		
dSP 1	Low Display Value in Pounds/Kilos	*0		
InP 2	High Input reading in MA	*20.000		
dSP 2	High Display Value in Pounds/Kilos	*10000		

#### 1-INP Input Parameters

\*Typical values for a 4-20ma sensor and a 0-10000 lb. Calibration.

#### 2-FNC External Input and Function Key Parameters

Display	Parameter	Setting
USr-1	User Input 1	PLOC
USr-2	User Input 2	nO
USr-3	User Input 3	nO
F1	Function Key 1	nO
F2	Function Key 2	nO
rSt	Reset Key	nO
Sc-F1	Secondary Function Key 1	nO
Sc-F2	Secondary Function Key 2	nO

#### 3-LOC Parameter Lockouts

Display	Parameter	Setting
HI	Maximum Reading Display	LOC
LO	Minimum Reading Display	LOC
tOt	Total Reading Display	LOC
SP-1	Setpoint 1 – Entry Enabled	Ent
SP-2	Setpoint 2	LOC
SP-3	Setpoint 3	LOC
SP-4	Setpoint 4	LOC
CodE	Security Code	0

#### 4-SEC Secondary Function Parameters

These parameters are not used at this time.

#### 5-tOt Totalized Parameters

These parameters are not used at this time.

#### 6-SPt Setpoint Parameters

Display	Parameter	Setting
SPSEL	Select Setpoint	SP-1
Act-1	Action for Setpoint – Absolute High	Ab-HI
SP-1	Setpoint Value – Alarm Limit	*1000
Src-1**	Setpoint Source – Net Input Value	rEL
HYS-1	Setpoint Hystersis	2
tOn-1	On Time Delay	0.0
tOF-1	Off Time Delay	0.0
Out-1	Output Logic	Nor
rSt-1	Reset Action	Auto
Stb-1	Standby Action	no
Lit-1	Output Panel Light	nor

\* Alarm limit value that can be changed from front panel after programming

\*\* Feature only available on the newer meters

#### 7-SrL Serial communications Parameters

Display	Parameter	Setting
bAUD	Baud Rate	2400
dAtA	Data Word Length	7
PAr	Parity	Odd
Addr	Meter Address	2
Abrv	Abbreviated Printing	no
OPt	Options	no

#### 8-Out Analog Output Parameters

Display	Parameter	Setting
tYPE	Analog Type	4-20
AS In	Analog Assignment	InP
An-LO Analog Low Scale Value		0
An-HI	Analog High Scale Value	10000
udt	Update Time	0.0

#### 9-FCS Factory Service Parameters

Display	Parameter	Setting
d-LEv	Display Intensity Level	3
CodE	Factory Service Code	*** 50

\*\*\* Normally will show 50. To clear all setting to factory defaults enter 66.

# 4 DTLS Through Warrior Software

#### **USB** communications

The Warrior software communicates with the Depth Tension Line Speed Panel through USB. The panel needs to have a USB cable connected to the computer or through the computer through a USB hub (such as in the Scientific Data Systems, Inc. Interface Panel). The DTLS panel can be found in the Windows Device Manager as a Human Interface Device.

The Depth panel communications must be enabled through the Warrior Depth Control Window by Selecting USB for the Depth Panel - Panel Type and clicking on the [Connect] button.

	Depth Control     X
■ Depth - □ ×	Depth       New Depth       Image: Constraint of the second
Feet 63.5 ft/min Control	Depth Panel       Panel Type       Connect         USB       Panel Type       Get         Update to depth panel       Get         Differential       0.0       Mute
	Hoist Config Apply Close

Fig. 4.1 Connecting to Depth Panel

Once the panel has been connected to the software, click the [Config] button to bring up the Depth Configuration Window.

Depth Configuration		×
Parameters Correction 0 Pt/1000 Encoder Res. 120 Pulse/Rev Wheel Size 1 Pt/Rev	Depth Panel Alarms     Value     On/Off       Surface Proximity     5.0        Line Overspeed     50.0        Line Tension     1000.0	
For up log, logging speed is positive     Depth Panel     Depth Scale Factor     Speed Scale Factor	Get Set Test Alarm 1 Alarm 2 Alarm 3 Alarm 4	
Divider (Jr 5 setting)     J       Image: Get     Get       Perf stop depth range     Mithin +/-       0.3     ft       Close     Alarms	Alarm Editor Edit All Alarms	

Fig. 4.2 Depth Configuration Window

If the [Apply] button is clicked in the parameters section, new scale factors will be written to the Depth 1 meter, Depth 2 meter, and the Line Speed section of the Depth 2 meter. The "Reverse" check box reverses the depth direction of the depth panel meters and the depth direction of the Warrior software.

By clicking on the [ Get ] button in the Depth Panel section, the scale factors of the meters may be read to verify settings. The "Reverse" check box reverses the depth direction of the depth panel meters only.

The alarms in the depth panel may be set through the Depth Panel Alarms section. Enter the desired alarm limits in the value windows and select whether the alarm is to be on or off (off sets unreachable limits in the panel meters) then click the [Set ] button to set the alarms. Current alarm values may be read by clicking the [Get ] button. Note that no alarms will sound until at least one depth pulse has been received after the panel has been turned on.

The Test section has several alarm sequences that may be tested. Again note that the alarms will not sound until the panel has received at least one depth pulse after the panel has been turned on.

# **5 DTLS Hardware**

#### Schematic 1

Encoder pulses are buffered and fed into a quadrature detector ICI used to detect ppr and direction before being divided down by the jumper selection at J5. The buffered outputs as well are the outputs of the quadrature detector are all buffered out through IC7 to J1.

The voltage output to the encoder is selected by the J7 and is either +12v or +5v. IC6 is a voltage input detector, if more than +12v is applied to the panel SCR Q1 is triggered shorting the input power and tripping the fuse.

U1 is a 12v to 5v converter used to provide circuit power as well as encoder panel is selected.

#### Schematic 2

IC11 and IC10 handle the RS232 communications between the main board and the two depth displays. The received signal is fed into a nand gate were any serial data input from the tension meter via IC12 are merged then inverted and sent into the micro controller on pin 30. The TX output to the meters is also fed out to the meters through IC10, 11 and 12.

Input alarms from the tree meters enter on J9, they are connected to pull up resisters before being buffered into the micro controller. Outputs from the micro controller to the son and lmp alarms are also buffered out through J9.

The combination of IC13 and IC3 is used to prevent the occurrence of false alarms.

#### Schematic 3

This page contains the micro controller and associated hardware.

IC9 is the serial EPROM used to program the microcontroller on power up.

IC15is a diode protection for the incoming and outgoing USB signals.

IC14 is a 5v to 3.3v dc to dc converter used to power the microcontroller, EPROM and usb protection circuit.

Fig 6.1 Schematic page 1



Fig 6.2 Schematic page 2





Fig 6.4 PCB









# **6 DTLS Hardware**

The following figure shows the rear connects on the GEM 20 Depth Meter and the GEM 42 Line Speed Meter.



## WIRELIST DEPTH PANEL - USB

Rear Panel Connectors

J1	DC Powe	ər in		
	J1-A	J10-1		+12V Battery
	J1-B	SW 2-2/5	GND LUG	Chassis Ground
J2	Line Wei	ght Input from T	ransducer	
	J2-A	J2-E		GND
	J2-B	J11-3		4-20ma Signal
	J2-D	J11-4		+12V Excite
	J2-E	J5-F	J2-A	GND
J3	Line Wei	ght Retransmit t	o System	
	J3-C	J11-10	*	PAX Analog 19-(0-20)Out
	J3-D	J11-9		PAX Analog 18 +(0-20)Out
J4	External	l amp or Alarm		
	J4-A	PCB J2-2	BZ+	+12V Reg
	J4-B	PCB_J9-8		External Lamp
15	Quadrati	re Encoder Inn	+	
99		DCD 12 1	n.	Encodor A
	IS D	DCD la a		Encoder R
	J5-D	DCD 10 0	Dolay 1	Encoder Dewor
	J5-F	J2-E	J6-F	GND
16	Duffered	Ouedrature to S	unteres.	
90	Builered		ystem	Duffored A
	JO-A			Duffered D
	J6-B	J5-F	GND LUG	GND
.17	Alarm Dr	alav		
	.17-A	Rolav-7		Relay NC
	J7-R	Rolay-9		Relay Wiper
	J7-C	Relay-11		Relay NO
.17	Rufforod	Quadraturo Soa	re (Ontional, 17 Wiring)	
	Dullereu		the (Optional 37 Winnig)	Buffored A
	17 0			Duffored D
	J7-C	J6-F	GND LUG	GND
10		the Orementer		
99	USB Por	t to Computer	ard	
	Connecte	EQ DIRECTATIO RO	aru	

J10	Front Pan	el Controls	
	J10-1	J1-A	+12V Battery
	J10-2	BZ+	Reg 12V - LED
	J10-3	PCB_J9-5	Mute Switch
	J10-4	PCB_J2-4	Switched 12 Volt
	J10-5	PCB_J8-2	Led Control
	J10-6	GND LUG	GND
P10	Front Pan	el Controls	
	P10-1	F1-2	+12V Battery
	P10-2	LED RED	Reg 12V - LED
	P10-3	SW 4-2	Mute Switch
	P10-4	SW 1-1	Switched 12 Volt
	P10-5	LED WHT	Led Control
	P10-6	SW4-1	GND
14.4	Line Terre	ian Matas	
JII	Line Tens	ION Meter	Bag 12 Volt
	J11-1	PUB_J2-1	CND
	311-2		4 00ma Signal
	J11-3	J2-B	4-20ma olghai
	111.5	J2-D GM/0.0	+ 12V EXCILO
	111.6		DD.
	111-7		DR.
	.111.8		GND
	111.0		PAX Analog 18 +/0.20)Out
	.111-10	-19-C	PAX Analog 10 +(0-20)Out
	.111-11	GNDLUG	GND
	.111-12	PCB .lg.4	TNS ALM
	011-12	100_08-4	Inches
P11	Line Tens	ion Meter	
	P11-1	PAX-1	Reg 12 Volt
	P11-2	PAX-2	GND
	P11-3	PAX-4	4-20ma Signal
	P11-4	PAX-6	+12V Excite
	P11-5	PAX-8	PGM Mode
	P11-6	PAX-12	DR+
	P11-7	PAX-13	DR-
	P11-8	PAX-14	GND
	P11-9	PAX-18	+(0-20)Out
	P11-10	PAX-19	-(0-20)Out
	P11-11	PAX-20	GND
	P11-12	PAX-21	TNS ALM

PAX	Line Tension	n Meter		
-	PAX-1	P11-1		Reg 12 Volt
	PAX-2	PAX-7	P11-2	GND
	PAX-4	P11-3		4-20ma Signal
	PAX-6	P11-4		+12V Excite
	PAX-7	PAX-2		GND
	PAX-8	P11-5		PGM Mode
	PAX-12	P11-6		DR+
	PAX-13	P11-7		DR-
	PAX-14	P11-8		GND
	PAX-18	P11-9		+(0-20)Out
	PAX-19	P11-10		-(0-20)Out
	PAX-20	P11-11		GND
	PAX-21	P11-12		TNS ALM
		De	pth and Line Speed	
DP_IBA	DEPTH Mete	er TBA - Cont	rol RCP lo d	
	DP_TBA-3	LS_IBA-3	PCB_J2-1	+12V
	DP_TBA-5	UP_IBA-8	DP_IBC-5	GND DCM Mode
		DD TDA 10		CND
		DCD IQ 2	DF_TBA-5	Dopth ALM
	DP_TBA-10		LS_TBC_1	GND
	DP_TBA-11	PCB J1-1	20_100-1	Reset
	51_15111	105_011		1000
DP_TBC	Depth Meter	TBC - Depth		
	DP_TBC-1	DP_TBC-5	PCB_J2-3	GND
	DP_TBC-2	LS TBC-2	PCB J1-7	DIR
	DP_TBC-3	LS_TBC-3	PCB_J1-6	PPR
	DP_TBC-5	DP_TBA-5	DP_TBC-1	GND
DP_IBD	Depth Meter	TBD - Comm	lunications	Nata Camania tan
	DP_TBD-1	PCB_J6-2		Meter Communications
				Meter Communications
				Meter Communications
				Motor Communications
	DP_TBD-7	LS_TBD-3		Meter Communications
		20_1000		
LS TBA	Line Speed	Meter TBA - C	Control	
	LS TBA-3	DP TBA-3		+12V
	LS_TBA-5	LS TBA-8	LS_TBC-5	GND
	LS TBA-7	DP TBA-7	-	PGM Mode
	LS_TBA-8	LS_TBA-10	LS_TBA-5	GND
	LS_TBA-9	PCB J9-3	-	SPD ALM
	LS_TBA-10	LS_TBA-8		GND
LS_TBC	Line Speed	Meter TBC - D	)epth	
	LS_TBC-1	LS_TBC-5	DP_TBA-10	GND
	LS_TBC-2	DP_TBC-2		DIK
	LS_TBC-3	DP_IBC-3	10 700	PPR
	LS_TBC-5	LS_TBA-5	LS_IBC-1	GND

LS_TBD	Line Speed	Meter TBD - O	Communications	
	LS_TBD-1	PCB_J6-4		Meter Communications
	LS_TBD-3	DP_TBD-7		Meter Communications
	LS_TBD-4	PCB_J6-1		Meter Communications
	LS_TBD-5	DP_TBD-4		Meter Communications
	LS TBD-6	PCB J6-3		Meter Communications
	LS_TBD-7	DP_TBD-6		Meter Communications
		P	C Board Connectors	
PCB_J1	Encoder Co	nnections		
	PCB_J1-1	DP_TBA-11		Reset
	PCB_J1-2	J7-A	{Optional Wiring}	Buffered A
	PCB_J1-3	J7-B	{Optional Wiring}	Buffered B
	PCB_J1-4	J6-A		Buffered A
	PCB_J1-5	J6-B		Buttered B
	PCB_J1-6	DP_TBC-3		PPR
	PCB_J1-7	DP_TBC-2		DIR
	PCB J1-9	PCB J3-4	GND LUG	GND
PCB_J2	12 Volt Pow	er Distribution		
	PCB_J2-1	DP_TBA-3	J11-1	Reg 12 Volt
	PCB_J2-2	J4-A	00000000	Reg 12V - LED & Buzzer
	PCB_J2-3	DP_IBC-1	GND LUG	GND Cwitebool 40 Volt
	PGB_J2-4	J10-4		Switched 12 Volt
DCB 12	Encodor Co	proctions		
FCD_03	PCD 12 1	IF A		Encodor A
	PCB 13.2	J5-A		Encoder R
	DCD loo	JS-D		Encoder Bower
	PCB .12.4	PCB .11.0		GND
l	100_004	100_01-0		GILD
PCB J4	PAX Tensio	n Meter Comr	nunications	
	PCB_J4-1	J11-6		DR+
	PCB_J4-2	J11-7		DR-
PCB_J6	Depth Meter	r Communicat	ions	
	PCB_J6-1	LS_TBD-4		Meter Communications
	PCB_J6-2	DP_TBD-1		Meter Communications
	PCB_J6-3	LS_TBD-6		Meter Communications
	PCB_J6-4	LS_IBD-1		Meter Communications
PCB J8	Alarm Set L	ED		
	PCB J8-1			GND
	PCB J8-2	J10-5		Led Control

PCB_J9	Alarm Contr	ols	
	PCB_J9-1		
	PCB J9-2	DP_TBA-9	Depth ALM
	PCB_J9-3	LS_TBA-9	SPDALM
	PCB_J9-4	J11-12	TNS ALM
	PCB J9-5	J10-3	Mute Switch
	PCB_J9-6	Relay-22	Relay Control
	PCB_J9-8	J4-B	External Lamp
	PCB_J9-9	BZ-	Buzz Control

			Misc.	Items	
F1	Fuse				
	F1-2	SW 1-2			+12V Battery
	F1-2	P10-1			Fused +12V
SW1	Dowor on/o	#			
5111	SW 1-1	P10-4			Switched 12 Volt
	SW 1-2	F1-1			Fused +12V
SMO	Drogram M	odo			
3112	Program M	SW/0.5	II D		GND
	SW 2-2	J11 5	J1-D		DCM Mode
	SW 2-5	SW 2.2	II-R		GND
	SW2-6	DP_TBA-7	01-0		PGM Mode
SW4	Mute Buttor	1			
	SW4-1	P10-6			GND Muta Switch
	3004-2	P10-3			Mute Switch
LED	Alarm Indic	ator			
	RED	P10-2			Reg 12V - LED
	WHT	P10-5			Led Control
BUZZER					
	BZ+	J4-A	J10-2		Reg +12
	BZ-	PCB_J9-9			Buzz Control
GND LUC	}				
	PCB J2-3	PCB J1-9	J1-B	J6-F	
	J10-6	J11-2	J11-8	J11-11	
DELAY					
RELAT	Dolou 1				Control Voltage
	Polay-1	17-0			Rolay NC
	Rolay-9	J7-R			Relay Wiper
	Relay-11	J7-C			Relay NO
	Relay-22	PCB J9-6			Relay Control